

11/6/13 CCR Proposed Sampling Locations

Location #1 (S. of Star Rd) on 10th St

→ East side of the road could yield one sample location due to the crop on the land. Chat has been removed or washed out from the field. No evidence after ~20 ft off road or chat.

→ On west side, the line continues very degraded but chat is still present. Several RR pins + metal is present. (Check extent of access post. 10th street → could yield ~3 sample locations if access included.

Location #2 (on Greelawn east of 10th St)

→ North side of the road has a short, shallow dip right at the road (~10 ft from) and the line continues. Heavily vegetated and degraded line

→ South side is even more degraded and vegetated. Very little visible chat under leaf cover on ground



location

(Residential)

Location #3 on Wilkes Ave in
between 2nd + 4th St. after
diagonal 3rd St

West side of the road is sparsely
vegetated with tall grasses
that is visible with degraded
wood trees and some igneous
rocks in the mix.

Line continues until active line
East side is exposed "assumption"
with no vegetation. On a map,
it shows up as a road.

Chert is spread out in varying
distances from the line's
original setting.

followed chert road/trail to
Grant Street.

On EAST/N side of Grant St. →
heavily vegetated on each side
of the tracks. Track is clear
and chert is visible.

Continues east and curves
north past an industrial
plant

Location #4 on Ballard just south
of 19th Street ~~at the~~
in between barn & house

10th St
old
so
removed
re
the
t.
strives
chert
cont.
post.
d
17

= 10th St)

at
the
y
line

d
order

line might still exist?
Access is impeded by swamp ^{large piled}
West of the road has been ^{cut out}
remediated by BS PD contractor
East side has a gate w/ lock
but chat/line ore exposed
throughout curve. Visible
for 3+ sample locations.
sparsely vegetated w/ grasses.
Potential cattle issue. —
Check w/ landowner.

Location #5 on SE 30th Street, just
west of Bullard / 10th Street.

North side of road where
Abenamy property w/ line
was remediated as part of
BS PD remediation contract.
→ north side is gated & locked
and has a road.

~~Fract~~^{line} / chat is visible and
no vegetation.

Continues through property
and is visible for 3+ sample
locations - check w/ surv.

land owner to gate access.

No evidence of tracks, signs, etc
→ maintained as a farm
road

Boxer Springs for lunch 12 PM

Handwritten header text

Section 1: [Illegible]

[Illegible handwritten text]

Section 2: [Illegible]

Section 3: [Illegible]

[Redacted]

[Illegible handwritten text]

[Redacted]

[Illegible handwritten text]

[Illegible handwritten text]

[Illegible handwritten text]

[Redacted]

[Redacted]

[Illegible handwritten text]

[Redacted]

[Illegible handwritten text]

[Redacted]

[Illegible handwritten text]

[Redacted]

[Illegible handwritten text]

[Illegible handwritten text]

[Illegible handwritten text]

[Redacted]

[Illegible handwritten text]

[Redacted]

[Illegible handwritten text]

[Illegible handwritten text]

Dec 4
2003

Sold to Freeman

SW Rock & Chat Co. 1999
sold to [REDACTED]

Youngman Rock 1991
sold to SW Rock & Chat

[REDACTED] sold to
SW Rock & Chat

[REDACTED] → large
[REDACTED]

[REDACTED] - SW corner-ish
[REDACTED] - Appraisers) at the
Section 18 along 69 east side
→ metal-sided warehouse
in trees??
→ old mining buildings
at the corner 69 & 69 [NE]
- the same as the ones [corner]

1986

→ Trece Truett bought a building in May 2012 from the red box area in that corner of 1986 pic

C&S Equipment & Sales owned

→ Section 18 the washers & corporation structures

↳ 1984 Nanco end @ 3:30pm

Location 6 → visited previously in Crestline w/ pics of!

Location # 7 SE 80th ^{South of Old Hwy 96}

line is left as a grade with flooded valleys on each side

→ on east side of road = some hills created with the chert

→ on both sides of the road chert is visible w/ some leaf litter and heavily vegetated and trees along the line.

NE
corner

Location #8 on 90th St south of
old Hwy 96

West side of the road is clear for
a great distance until halted
by a bale of hay
Not treed or vegetated.

Chat is visible → access road
maintained
by land owner
east side of the road is the same
with higher grassy areas on either
side of the line of exposed
chat. There is a gate & chained
for access.

end @ 4:30pm

